

**Flow From Solid Stream Tips  
Hand Lines**

<u>Tip Size</u>	<u>Flows</u>
7/8" .....	150 GPM
15/16" .....	180 GPM
1" .....	200 GPM
1-1/8" .....	250 GPM
1-1/4" .....	300 GPM

**Flow From Heavy Stream  
Appliance Tips**

<u>Tip Size</u>	<u>Flows</u>
1-1/4" .....	400 GPM
1-3/8" .....	500 GPM
1-1/2" .....	600 GPM
1-3/4" .....	800 GPM
2" .....	1000 GPM

**Appliance Losses**

Heavy Stream start at .....	+10 PSI
Wyes .....	+5 PSI
Siamese .....	+5 PSI